


2019-01-22 10:17:02



IR\_2335.jpg

FLIR B660

404002896

#### Measurements


|     |         |
|-----|---------|
| Sp1 | 19.0 °C |
|-----|---------|

#### Parameters

|             |         |
|-------------|---------|
| Emissivity  | 0.95    |
| Refl. temp. | 17.1 °C |

#### Text annotations

2019-01-22 10:17:32



IR\_2337.jpg

FLIR B660

404002896

#### Measurements


|     |         |
|-----|---------|
| Sp1 | 20.0 °C |
|-----|---------|

#### Parameters

|             |         |
|-------------|---------|
| Emissivity  | 0.95    |
| Refl. temp. | 17.1 °C |

#### Text annotations

2019-01-22 10:18:04



IR\_2339.jpg

FLIR B660

404002896

#### Measurements


|     |         |
|-----|---------|
| Sp1 | 15.4 °C |
|-----|---------|

#### Parameters

|             |         |
|-------------|---------|
| Emissivity  | 0.95    |
| Refl. temp. | 17.1 °C |

#### Text annotations

2019-01-22 10:18:37



IR\_2341.jpg

FLIR B660

404002896

#### Measurements

|     |         |
|-----|---------|
| Sp1 | 13.2 °C |
|-----|---------|

#### Parameters

|             |         |
|-------------|---------|
| Emissivity  | 0.95    |
| Refl. temp. | 17.1 °C |

#### Text annotations

2019-01-22 10:19:10



IR\_2343.jpg

FLIR B660

404002896

#### Measurements

|     |         |
|-----|---------|
| Sp1 | 16.2 °C |
|-----|---------|

#### Parameters

|             |         |
|-------------|---------|
| Emissivity  | 0.95    |
| Refl. temp. | 17.1 °C |

#### Text annotations

2019-01-22 10:19:33



IR\_2345.jpg

FLIR B660

404002896

#### Measurements

|     |         |
|-----|---------|
| Sp1 | 18.0 °C |
|-----|---------|

#### Parameters

|             |         |
|-------------|---------|
| Emissivity  | 0.95    |
| Refl. temp. | 17.1 °C |

#### Text annotations