


2019-01-15 15:30:48



IR\_1369.jpg

FLIR B660

404002896

#### Measurements


|     |         |
|-----|---------|
| Sp1 | 15.6 °C |
|-----|---------|

#### Parameters

|             |       |
|-------------|-------|
| Emissivity  | 0.95  |
| Refl. temp. | -4 °C |

#### Text annotations

2019-01-15 15:31:41



IR\_1373.jpg

FLIR B660

404002896

#### Measurements


|     |         |
|-----|---------|
| Sp1 | 10.7 °C |
|-----|---------|

#### Parameters

|             |       |
|-------------|-------|
| Emissivity  | 0.95  |
| Refl. temp. | -4 °C |

#### Text annotations

2019-01-15 15:32:01



IR\_1375.jpg

FLIR B660

404002896

### Measurements


|     |         |
|-----|---------|
| Sp1 | 12.7 °C |
|-----|---------|

### Parameters

|             |       |
|-------------|-------|
| Emissivity  | 0.95  |
| Refl. temp. | -4 °C |

### Text annotations

2019-01-15 15:32:26



IR\_1377.jpg

FLIR B660

404002896

#### Measurements


|     |         |
|-----|---------|
| Sp1 | 13.7 °C |
|-----|---------|

#### Parameters

|             |       |
|-------------|-------|
| Emissivity  | 0.95  |
| Refl. temp. | -4 °C |

#### Text annotations

2019-01-15 15:33:13



IR\_1379.jpg

FLIR B660

404002896

#### Measurements


|     |        |
|-----|--------|
| Sp1 | 8.6 °C |
|-----|--------|

#### Parameters

|             |       |
|-------------|-------|
| Emissivity  | 0.95  |
| Refl. temp. | -4 °C |

#### Text annotations

2019-01-15 15:36:03



IR\_1381.jpg

FLIR B660

404002896

#### Measurements

|     |        |
|-----|--------|
| Sp1 | 8.9 °C |
|-----|--------|

#### Parameters

|             |       |
|-------------|-------|
| Emissivity  | 0.95  |
| Refl. temp. | -4 °C |

#### Text annotations